

THERMOSET MEMBRANE REPAIRS

SERVICE DESCRIPTION

D. C. Taylor Co. Service Technicians will identify and repair the following defects:

- Splits, tears, abrasions and cuts
- Seam laps and splices
- Deteriorated caulking and sealants
- Weathered, cracked or deteriorated penetration flashings
- Scupper and drain flashings
- Raised fasteners




DELIVERABLES

Completed Thermoset Membrane Repairs

Work Order Photo Album:

A report containing before and after photos of the repaired defects.



WHEN TO USE

- Membrane deficiencies could result in more costly repairs, insulation replacement or deck replacement.
- Roof leaks are impacting production, people or property within the facility.

FOR PRICING INFORMATION

Call or email D. C. Taylor Co. and ask for "Thermoset Membrane Repairs".

800.569.6271

service.products@dctaylorco.com

Note: D. C. Taylor Co. employees have been verified through the Department of Homeland Security, received OSHA 10 hr training within 60 days of hire, and trained in fall protection and personal safety.



D. C. Taylor Co.
www.dctaylorco.com

© 2010 D. C. Taylor Co. All rights reserved.